



PUNJAB STATE TRANSMISSION CORPORATION LIMITED
Regd. Office: PSEB Head Office, The Mall Patiala-147001, Punjab, India.
Corporate Identity Number: U40109PB2010SGC033814 (www.pstcl.org)

(Office of Chief Accounts Officer (Finance & Audit), ARR Section
3rd Floor, Shakti Sadan, Patiala)

Fax/Ph. No.0175-2970183 Email : fa@pstcl.org

To

PSEB Engineers' Association,
45, Ranjit Bagh, Near Modi Mandir
Passey Road, Patiala.

Memo No. 707 /CAO(F&A)/MYT-IIA

Dated: 27/2/2020

Subject: Additional Submission by PSEB Engineers' Association in Objection No. 03 on Petition no. 29/2019 filed by PSTCL before PSERC.

Ref: Your office Letter no. PSEBEA/Spl-1 dated 11.02.2020.

In response to letter under reference, please find enclosed herewith the reply of the additional comments submitted in objection no. 03 at Public hearing dated 03 Feb 2020 on subject cited petition filed by PSTCL before PSERC.

DA/As Above

o/ CAO (Finance & Audit),
c PSTCL, Patiala.
26/2/2020 26/2

708
27/2/2020 CC:
The Dy. Registrar, PSERC w.r.t. their Memo no. PSERC/Reg./2712 dated 13.02.2020.

DA/As Above

Reply to the Additional Submission by PSEB Engineers' Association.

Sub: Additional Submission by PSEB Engineers' Association on PSTCL's ARR/ Tariff Petition for 2020-21 to 2022-23, Review of 2019-20 and True up of 2018-19 (Petition no. 29/2019) at Public hearing on 03 Feb 2020 – Re conducting of 220KV Bhakra Jamalpur Line.

The Re Conductoring work of 220 KV Bhakra Jamalpur Line was planned 10 years back and BBMB had taken a conscious decision to carry out the re-conductoring of their own and had procured the conductor 10 years back. The conductor has been kept in open area and the drums had already worn-out. As such, the utilization of this conductor is a tough task and would result into damage of a considerable portion of conductor. BBMB has its own transmission wing and repeated tenders by BBMB have found no contractor to undertake the work because of severe Right-of-Way issues and as such PSTCL can't get into the same and only way out is that PSPCL should press upon BBMB to complete the work at the earliest.